Safety Issue Type: Recalls

January 17 2025 NHTSA Campaign Number: 25V019000

Loss of Drive Power from Battery Failure

Battery failure can result in a loss of electrical accessories, including the hazard lights, or cause a loss of drive power, increasing the risk of a crash.

NHTSA Campaign Number 25V019000

Manufacturer Ford Motor Company

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 272817

Summary

Ford Motor Company (Ford) is recalling certain 2021-2023 Bronco Sport and 2022-2023 Maverick vehicles. The 12-volt battery

may experience degradation and suddenly fail.

Remedy

Dealers will inspect and if necessary, replace the 12-volt battery, free of charge. Owner notification letters are expected to be mailed February 3, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S02. Vehicles in this recall were previously repaired under 24V-267 and will need to have the new remedy completed.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153) or go to nhtsa.gov.

Affected Products (5)

Vehicle

MAKE	MODEL	YEAR
FORD	BRONCO SPORT	2021-2023
FORD	MAVERICK	2022-2023

Associated Documents (3)

Recall 573 Report RCLRPT-25V019-5305.PDF 216.699KB https://static.nhtsa.gov/odi/rcl/2025/RCLRPT-25V019-5305.PDF

Recall Acknowledgement RCAK-25V019-9951.pdf 684.383KB https://static.nhtsa.gov/odi/rcl/2025/RCAK-25V019-9951.pdf

Manufacturer Notices(to Dealers,etc) RCMN-25V019-6738.pdf 37.604KB https://static.nhtsa.gov/odi/rcl/2025/RCMN-25V019-6738.pdf